
Assembly Instructions


Ultimate Folding Screen Portable Projection Screen by Draper


Patent Pending

























Caution: Make sure all hinges and joints are locked before raising screen to standing position.



Caution: Make sure screen is placed on level surface.

***Please Note:**
For easier surface attachment, start in one corner, then work your way around the frame.*

****Caution: Beware of pinch points.***



The ideal temperature range for assembling folding screens to prevent damaging the surface is 68°-78° F (20°-26° C). Assembling below recommended temperatures may damage surface and void warranty.

Always fold with snaps face-to-face. Do not permit screen fabric to contact border material or snaps when folded. Store in pouch provided.

If you encounter any difficulty installing or servicing your Ultimate Folding Screen by Draper, *call your dealer or Draper, Inc., Spiceland, Indiana, (765) 987-7999 or fax (765) 987-7142.*

DRAPER®

411 S. Pearl St., Spiceland, IN 47385 USA ▮ 765-987-7999
www.draperinc.com ▮ fax 765-987-7142

 Form UltimateFoldingScreen_Inst11 Printed in U.S.A.